


## 1854527 Bradbourne Table

### **Parts and Hardware List**

A.	Top Assembly	1 pc
B.	Legs	4 pcs
C.	Bottom Assembly	1 pc
D.	Flat Washers	12 pcs
E.	Lock Washers	12 pcs
F.	Short Allen Head Bolts	8 pcs
G.	Long Allen Head Bolts	4 pcs
H.	Allen Head Wrench	1 pc

- \* Please make sure that you have all the parts and hardware indicated before you begin assembly of this item.
- \* Use the hardware illustrations to determine correct piece and size.
- \* This item should be assembled on a soft surface to prevent scratching the finish during assembly.
- \* This item may require periodic tightening.


# **Hardware Illustrations**





F. Short Allen Head Bolt

D. Flat Washer





G. Long Allen Head Bolt

E. Lock Washer


Page 1 of 2 R1-02-17-05



## 1854527 Bradbourne Table

#### **Attach Legs and Bottom Assembly**

- 1. <u>Attach Legs (B)</u> Turn the Top Assembly (A) upside down. Align the pre-drilled holes of the Legs (B) with pre-threaded holes of the Top Assembly (A). Secure, but do not fully tighten, with Short Allen Head Bolts (F), Flat Washers (D) and Lock Washers (E) and using the Allen Head Wrench (H).
- 2. <u>Attach Bottom Assembly (C)</u> Align the pre-drilled holes on the Bottom Assembly (C) with the pre-threaded holes on the bottom of the Legs (B). Secure with Long Allen Head Bolts (G), Flat Washers (D) and Lock Washers (E) and using the Allen Head Wrench (H).
- 3. Tighten all bolts on the Legs (B) at this time.



Page 2 of 2 R1-02-17-05